
DiMarzio, Inc.

1388 Richmond Terrace, PO Box 100387, Staten Island, NY 10310, Tel(718)981-9286, Fax(718)720-5296

1 HUMBUCKER 2 SINGLES

Resistor added to lower DCR with N & M pickups on



All other pickup wires not shown or mentioned go to ground. Note: Tailpiece should be connected to common ground. All grounds 🛓 must be connected.

Copyright (C) 2003 DiMarzio, Inc. All rights reserved